

Motor winding B		black
Motor winding C		yellow

GND		black
Hall sensors A		blue
Hall sensors B		green
Hall sensors C		white

